



Project report

Collapsed coastal road – Cumbria – North England

Project description

Coastal road in Cumbria, North England is collapsing due to severe storms and wave action.

AquaRockBag® is used as a **temporary measure to support the road and prevent scour** during winter 2020/2021.



Internationale Geotextil GmbH

Am Bahnhof 54
27239 Twistringen (Germany)

Phone: +49 (0) 4243 9288-20

Fax: +49 (0) 4243 9288-22

Email: s.roess@roessgroup.com



Internationale Geotextil GmbH