



ROESS_group





Project report
Collapsed coastal road
Cumbria – North England



Project description

Coastal road in Cumbria, North England is collapsing due to severe storms and wave action.

AquaRockBag® is used as a temporary measure to support the road and prevent scour during winter 2020/2021.



